

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

DATE: 7/21/86

RECEIVED  
EPA REGION VI

SUBJECT: Potential Hazardous Waste Site

1986 JUL 23 AM 8:08

FROM: Keith Bradley, FIT RPO  
Hazardous Waste Section (6E-SH)

SUPERFUND BRANCH

TO: Martha McKee, Chief  
Compliance Section (6H-ES)

Site Name: Lincoln Properties  
Location: Austin, TX  
Hazard No.: TX 20591  
TDD No.: RO6-8604-17

TXD 981-155 911  
2 Ref Sa vol 1

A. Deliverables:

- |   |  |
|---|--|
| 1. Preliminary Assessment (Form 2070-2) | attached ( )                                 |
| 2. Site Inspection Report (Form 2070-3) | attached ( )                                 |
| 3. Sampling Inspection Report           | attached <input checked="" type="checkbox"/> |
| 4. Other: <u>Recon</u>                  | attached <input checked="" type="checkbox"/> |

B. Were drinking water wells sampled? Yes ( ) No ☒

C. Analytical Data:

- |                         |  |
|-------------------------|--|
| 1. None collected       | <input checked="" type="checkbox"/>          |
| 2. Field data           | <input type="checkbox"/>                     |
| 3. Contract lab results | attached <input checked="" type="checkbox"/> |
| 4. Houston lab results  | attached ( )                                 |

D. Comments:

FIT recommends that the State of Texas  
be allowed to continue the lead at this site.  
NO further FIT action is required.

SUPERFUND  
FILE

FEB 12 1993

REORGANIZED

cc:(circle) Cabra (6W-S)  
Gazda (6E-E)  
Taylor (6H-CE)

9417765

